Bruhath Bangalore Mahanagara palike,		
	Inspection Report	
1	Name of work	Construction of Zym Building and Library Building at Jalahalli in ward No.16
2	Administration Approval & Date	EE/RRND/AS/121/2015-16 Dtd:29-10-2015 by EE (RRND)
3	Technical Sanction Estimate No.& Date	CE/RRNZ/TS/184/2015-16 Dtd:30-10-2015 by CE (RRNZ)
4	Estimate Amount	Rs.30.00 Lakhs
5	Job Code No.	016-15-000054
6	P-Code	P-3089
7	Agreement No & date	EE/RRND/AGMT/107/2015-16 Dtd.16-01-2016.
8	Work order Number & Date	EE/RRND/Wo No./107/2015-16 Dtd.16-01-2016.
9	Contract Amount as per Agreement	Rs.26,53,500/-
10	Bill Amount	Rs.26,53,500/-
11	B.R. No. & Date	-
12	Agency	Sri.M.Manjunath
13	M.B. Number & Page No. of Measurement recordes	5247/16-17 Pages No. 524667 to 524680
14	Date of Inspection	11-10-20017
15	Enclosures	1)...8..... Number of photos taken during inspection
16	Inspection Report	The above site has been Inspected by me, along with the Concerned person as per EE (RRND) Lr No EE/RRN/JR/527/17-18 Dated 11-10-2017. The Items indicated in the MB, which are Suseptible for measurements have been checked and found to be satisfactory

EE, Jalahalli, RR Nagara Zone.

ರಾಜರಾಜೇಶ್ವರಿನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು - [illegible]

(R.Sathyanarayana) 11/10/2017
Inspection Report officer,

Scanned by CamScanner